



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 6th June 2015.