

<u>Close-up:</u> Illegal fitting on 28" Bomu-Bony Trans Niger Pipeline at Bodo West. Picture was taken during Joint Investigation of 26<sup>th</sup> April 2015.