

Overview: Part of spill impact n 14" Okordia – Rumuekpe Pipeline Right of Way at Akinima. Picture was taken during Joint Investigation of 20th May 2015.



<u>Close-up:</u> Illegal fitting on 14" Okordia – Rumuekpe Pipeline at Akinima. Picture was taken during Joint Investigation of 20th May 2015.

1