



Overview: Part of spill impact on 20" Otumara –Escravos Pipeline Right of Way at Ugboegungun
Picture was taken during Joint Investigation of 16th August 2017.



Close-up: Illegal fitting on 20" Otumara –Escravos Pipeline at Ugboegungun
Picture was taken during Joint Investigation of 16th August 2017.