



Overview: Part of spill impact on 12" Imo River-Ogale Pipeline at Komkom. Picture was taken during Joint Investigation of 10<sup>th</sup> March 2017.



Close-up: Leaking Illegal fittings on 12" Imo River-Ogale Pipeline at Komkom. Picture was taken during Joint Investigation of 10<sup>th</sup> March 2017.