



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline at Elimgbu. Picture was taken during Joint Investigation of 18<sup>th</sup> March 2017.



Close-up: Leaking Illegal fitting on 28" Nkpoku-Bomu Pipeline at Elimgbu. Picture was taken during Joint Investigation of 18<sup>th</sup> March 2017.