



Overview: Part of spill impact on 6" Obigbo North-Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 1<sup>st</sup> April 2017.



Close-up: Illegal fitting on 6" Obigbo North-Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 1<sup>st</sup> April 2017.