



Overview: Extent of the spill incident impact on 24" UPS-Rapele trunkline at Ugbokodo.
Picture taken during JIV of 6th April, 2011



Close-up: Illegally welded points on 24" UPS-Rapele trukline at Ugbokodo. Picture taken during JIV of 6th April, 2011.