



- Overview: Extent of the spill incident impact on 8in Isimiri Pipeline at Umuaghala. Spill site showing oil theft hose still attached to illegal off take point.



Close-up: Spill due to tampering on 8in Isimiri Pipeline at Umuaghala. Pictures taken during JIV of 12th April, 2011.