



Overview: Extent of the spill incident impact at 12" Imo 2 – Ogale Pipeline route in Owaza .  
Picture was taken during JIV of 24 April 2011



Close-up: Illegally welded points on 12" Imo 2 – Ogale Pipeline at Owaza. Picture was  
taken during JIV of 24 April 2011