



Overview: Extent of the spill incident impact at Oguta Well 17L flowline at Otuweneke-Umuayata. Picture was taken during JIV of 10 May 2011.



Close-up: Hacksaw cut on Oguta Well 17L flowline at Otuweneke-Umuayata. Picture was taken during JIV of 10 May 2011.