



Overview: Part of spill impact on 12" Imo River-Ogale Pipeline at Komkom. Picture taken during Joint Investigation on 4th August, 2011



Close-up: Illegally welded points on 12" Imo River-Ogale Pipeline at Komkom . Picture taken during Joint Investigation on 5th August, 2011