



Overview: Part of spill impact on 16'' Egbema -Asa Pipeline route at Ekpeagha . Picture taken during Joint Investigation of 27-28<sup>th</sup> August, 2011



Close-up: Spill due to illegal fitting on 16'' Egbema -Asa Pipeline at Ekpeagha . Picture taken during Joint Investigation of 27-28<sup>th</sup> August, 2011