



Overview: Part of spill impact on 6" Utorogu-Ughelli West gasoline at Iwhrekan. Picture taken during Joint Investigation of 25<sup>th</sup> August, 2011.



Close-up: Spill due to damage by 3<sup>rd</sup> party equipment on 6" Utorogu-Ughelli West gasoline at Iwhrekan. Picture taken during Joint Investigation of 25<sup>th</sup> August, 2011.