



Close-up: Illegal fittings on 12" ImoRiver-Ogale pipeline at KomKom. Picture was taken during Joint Investigation of 11th November, 2011.



Close-up: Illegal fittings on 12" ImoRiver-Ogale pipeline at KomKom. Picture was taken during Joint Investigation of 13th November, 2011.



Close-up: Illegal fittings on 12" ImoRiver-Ogale pipeline at KomKom. Picture was taken during Joint Investigation of 17th November, 2011.