



Overview: Part of spill impact on 14" Okordia-Rumuekpe pipeline at Ikarama. Picture taken during Joint Investigation of 29th August, 2011.



Close-up: Spill due to hacksaw cut on 14" Okordia-Rumuekpe pipeline at Ikarama. Picture taken during Joint Investigation of 29th August, 2011.