



Overview: Part of the spill impact on 10" Ekulama-Sanbarth pipeline at Sanbarth. Picture taken during Joint Investigation of 28<sup>th</sup> August 2011



Close-up: Spill point due to corrosion on 10" Ekulama-Sanbarth pipeline at Sanbarth. Picture taken during Joint Investigation of 22<sup>nd</sup> September, 2011