



Close-up: Spill due to hacksaw cut on Akaso Well 10L flowline at Cawthorne Channel.  
Picture taken during Joint Investigation of 16<sup>th</sup> August, 2011.