



Overview: Part of spill impact on 12" Adibawa-Okordia pipeline at Ikarama. Picture taken during Joint Investigation of 26th August, 2011.



Close-up: Spill due to hacksaw cut on 12" Adibawa-Okordia pipeline at Ikarama. Picture taken during Joint Investigation of 26th August, 2011.