



Overview: Part of spill impact on 10'' Diebu creek-Nun River Pipeline route at Oporoma . Picture taken during Joint Investigation of 1<sup>st</sup> September, 2011



Close-up: Spill due to drilled hole on 10'' Diebu creek-Nun River Pipeline at Oporoma. Picture taken during Joint Investigation of 1<sup>st</sup> September, 2011