



Overview: Part of spill impact at spill point A on 14in Okordia-Rumuekpe pipeline right of way at Ikarama. Picture taken during Joint Investigation of 6th August, 2011.



Close-up: Spill due to hacksaw cut on 14in Okordia-Rumuekpe pipeline at Ikarama. Picture taken during Joint Investigation of 6th August, 2011.