



Close-up: Spill due to hacksaw cut on Adibawa-Okordia pipeline at Ikarama. Picture taken during Joint Investigation of 8<sup>th</sup> August, 2011