



Overview: Part of spill and fire impact on 14in Okordia-Rumuekpe pipeline right of way at Ikarama. Picture taken during Joint Investigation of 19th August, 2011.



Close-up: Spill due to hacksaw cut on 14in Okordia-Rumuekpe pipeline at Ikarama. Picture taken during Joint Investigation of 19th August, 2011.



Close-up: Spill due to hacksaw cut on 14in Okordia-Rumuekpe pipeline at Ikarama.
Picture taken during Joint Investigation of 19th August, 2011.