



Overview: Part of spill impact on Ogini Well 4T 4" Flowline at Ovrode. Picture taken during Joint Investigation of 9th September, 2011



Close-up: Spill due to Complete Rupture on Ogini Well 4T 4" Flowline at Ovrode. Picture taken during Joint Investigation of 9th September, 2011