



Overview: Part of spill impact on 10" Diebu Creek pipeline right of way at Oporoma. Picture was taken during Joint Investigation of 17<sup>th</sup> December, 2011.



Close-up: Spill due to illegal fitting on 10" Diebu Creek pipeline at Oporoma. Picture was taken during Joint Investigation of 17<sup>th</sup> December, 2011.