



Overview: Part of spill impact on 16" NunRiver-Kolocreek pipeline right of way at Aguobiri. Picture was taken during Joint Investigation of 19th December, 2011.



Close-up: Hacksaw cut on 16" NunRiver-Kolocreek pipeline at Aguobiri. Picture was taken during Joint Investigation of 19th December, 2011.