



Overview: Location of illegal fittings on 24" Nembe Creek pipeline right of way at Nembe Bassambiri. Picture was taken during Joint Investigation of 30th December 2011.



Close-up: Illegal fitting on 24" Nembe Creek pipeline at Nembe Bassambiri. Picture was taken during Joint Investigation of 30th December 2011.