



Close-up: General location of tear at 6'o clock position on Bonny-Oloma Well2L flowline at Oloma. Picture was taken during Joint Investigation of 9th December, 2011.