



Overview: Part of spill impact on 18" Assa-Rumuekpe pipeline right of way at Awara. Picture was taken during Joint Investigation of 24<sup>th</sup> December 2011.



Close-up: Illegal fitting on 18" Assa-Rumuekpe pipeline at Awara. Picture was taken during Joint Investigation of 24<sup>th</sup> December 2011.