



Overview: Extent of the spill incident impact at 8" Obigbo-North Pipeline route in Obigbo. Picture was taken during JIV of 16 February 2011



Close-up: Illegally welded point on 8" Obigbo-North Pipeline in Obigbo. Picture was taken during JIV of 16 February 2011