



Overview: Extent of the spill incident impact at 20" Kolocreek – Rumuekpe Pipeline route in Ogbogolo . Picture was taken during JIV of 12 February, 2011



Close-up: Illegally welded points on 20" Kolocreek – Rumuekpe Pipeline in Ogbogolo. Picture was taken during JIV of 12 February 2011