



Overview: Extent of the spill incident impact at 28" Bomu – Bonny Pipeline route in Bodo .
Picture was taken during JIV of 10 February 2011



Close-up: Illegally welded points on 28" Bomu – Bonny Pipeline in Bodo. Picture was taken during JIV of 11 February 2011