



No. 01588

A. GENERAL INFORMATION:

1. Spill incident Number: (9775) 672654
2. Name of Location OLOMORO COMPRESSOR STATION 2
3. Name of nearest community OLOMORO
4. State DELTA LGA ISOKO SOUTH
5. Type of Production facility/Installation COMPRESSOR STATION Asset owner /District NWL 2

B. INCIDENT INFORMATION:

6. Details of incident
- a. Date of incident 14/06/2011 @ 11:30 HRS
- b. Date/Period of investigation, 16/06/2011 @ 12:20 HRS
- c. Description of spill point environment
- | | | |
|--|---|---|
| <input checked="" type="checkbox"/> Firmed soil | <input checked="" type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Loose soil | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Previously excavated area | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Under water | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Swampy | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Exposed pipe surface | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
- d. Description of leak point (tick as applicable);
- | | | |
|--|------------------------------|---|
| <input type="checkbox"/> Drilled hole, | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Hack saw cut, | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Explosive tear, | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Inward dent, | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Well head tampering | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve, | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Missing pipeline (flowline) | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Third party tampering with Clamp Bolt/Nut, | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Third party tampering with valve setting, | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Third party tampering with flange Nuts/bolts, | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Corrosion, | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
- Type: _____
- | | | |
|--|---|---|
| <input checked="" type="checkbox"/> Saver-pit over flow, | <input checked="" type="checkbox"/> [Y] | <input type="checkbox"/> [N] |
| <input type="checkbox"/> Surge vessel overflow, | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Outward dent | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |
| <input type="checkbox"/> Others (specify) <u>EQUIPMENT FAILURE</u> | <input type="checkbox"/> [Y] | <input checked="" type="checkbox"/> [N] |

e. Spill point coordinates

Northing: 161517 M Easting: 416641 M



No. 1588

C. RISK/DAMAGE ASSESSMENT

7. Type of environment of spill site:

- Land
- Swamp
- water

Type of environment of which oil has spread:

- Land
- Swamp
- water

8. Distance from the nearest sensitive habitat

- Government reserved and designated protected area [NILm]
- Drinking water source [NILm]
- Built up area [NILm]
- Farmlands [2,m]
- Fish Farm/Pond [NILm]
- Fishing net [NILm]
- Others (specify).

9. Containment measures put in place;

- Booms [X] [N]
- Trench [Y] [N]
- Dyke [Y] [N]

Others: _____

10. Any pictures or video coverage? [X] [N]

11. Was there any disruption to the investigation? [Y] [N]

If yes give brief description:

NOT APPLICABLE

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

A. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments



B. Crops/Economic Trees

S/N	Types of crops	Young	Medium	Matured	Quantity	Comments
1	PLANTAIN	✓			10	


C. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
		NONE WITHIN AREA	OF IMPACT	

D. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
		NONE WITHIN AREA	OF IMPACT	

E. GRAPHIC DESCRIPTION OF LEAK POINT (Details should be contained in leak repair report)





No. 1538

G. INCIDENT INFORMATION:

17 Impacted Area Details

- a. Total calculated area of impact 77.5 M²
 - Impact within SPDC R.O.W 77.5 M²
 - Impact outside R.O.W _____

18 Volume of oil recovered before completion of JIV (V_{recj}):

Recovered oil V _{recj} :	<u>NIL</u>	barrels
-----------------------------------	------------	---------

19. Computation of the residual volume on site

a. Computation of the volume of pooled free phase oil (on land or confined water body).

- i. Area (m²) occupied by pool of free phase oil 39 M²
- ii. Average Depth (m) of pool of free phase oil 0.002 M
- iii. EMULSIFICATION FACTOR IS 60%
Volume of pooled of free phase oil. V_{pool}:

<u>0.2</u>	barrels
------------	---------
- iv.

b. Computation of volume of infiltrated oil in the soil (V-3).

- i. Area (m²) covered by the oil: 38.5 M²
- ii. Average Depth (m) below ground surface of infiltration of oil: 0.12 M
- iii. Soil type: LATERITE
- iv. p_e (effective porosity of the soil): 20%
- v.

Volume of infiltrated oil. V _{int} :	<u>5.81</u>	barrels
---	-------------	---------

20. Computation of volume of oil on open water based on standard coloration.

	Thickness (mm)	Percentage coverage	Volume (m3)
Barely Visible	0.00004		
Silvery	0.00008		
Slight Colour	0.00015		
Bright Colour	0.0003		
Dull	0.001		
Dark	0.002		
Black oil	0.1		
Emulsion (30% Oil)	1		
	Percent Total	100%	Total Volume

bbi

Spill Factors from USCG FOG (2000 Edition)



Volume of oil on open water V_{wat} :

NIL

barrels

21. Calculation of evaporated volume:

i. Oil type: BONNY MEDIUM

ii. E-Factor: 15%

iii.

Volume of evaporated oil V_{vap} :

1.06

barrels

Oil Type		Bonny Light	Bonny Medium
		E-Factor	E-Factor
Period Since Oil Spill	<1 day	10%	5%
	1-7 days	25%	15%
	>7 days	40%	25%

9. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{vap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls)$

(1.06 + 5.81 + 0.2)

$V_{Est}(bbls) =$

7.07 BBL

10. Net Total Estimated Spilled Volume $VEst(bbls) = V_{vap}(bbls) + 0.6*V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls)$

$VEst(bbls) =$

7.07 BBL

* Calculation of the respective estimated volume is to done using the new spill estimation software on site

* Conversion of m3 to barrel is Total volume VT (m3) x6.29

* Emulsification factor for spill on water to consider is 60% of volume of oil.

This report was filled and signed on the 16/06/2011 at incident site by joint investigation representative from

- Host Community
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:
- Shell Petroleum Development Company [SPDC]:

Tick as applicable