No. 00385

A. GENERAL INFORMATION:			
1. Spill incident Number: ————————————————————————————————————	398		
10" Acca Dulla	IEKDE I	PIDEL INE	
-		LII WELINE	
3. Name of nearest community	(A		
4. StateLGA	TAHO	TI-EGREMA	4
4. State LUA	1 1	UC /P/NECD	
5. Type of Production facility/Installation PIPELINE Asset o	wner /District 🚨	LIGHT LINEST	
B. INCIDENT INFORMATION:			
6. Details of incident a. Date of incident 25 TH JUNE,	2011		
b. Date/Period of investigation, 27 TH JUNE			
c. Description of spill point environment			
☐ Firmed soil [Y] [N	- ,		
I_I > I_v			
☐ Previously excavated area [Y] [N			
	1		
	1		
d. Description of leak point (tick as applicable);	•		
□ Drilled hole,	[Y] / [N] .	
☐ Hack saw cut,	[Y] [N		TOINT
☐ Explosive tear,	[Y] [N	Y	_
□ Complete Rupture		INVESTI	AATION
☐ Inward dent,	[Y] [N, [Y] [N		VE
☐ Well head tampering	[Y] [N [Y] [N		TC.
☐ Failed Weld-on illegal hot tap valve,☐ Missing pipeline (flowline)	[Y] [N		NT
☐ Crude oil theft (illegal bunkering) point,	[Y] [N	V	,
☐ Third party tampering with Clamp Bolt/Nut,	[Y] [N	SPILL	CAW
☐ Third party tampering with valve setting,	[Y] [N	¥. —	T- 0=
☐ Third party tampering with flange Nuts/bolts,		HOUND	TO BE
□ Corrosion, Type: NoT APPLIC	ARI E.	DUE	To
☐ Saver-pit over flow,	[Y] [N	1	.05
☐ Surge vessel overflow,	[Y] [N		HRD
Outward dent Others (specify). NOT APPLICATE	RIF [Y] [N	PAR	TY
Uthers (specify).	ماليان ا	INTERFE	•
e. Spill point coordinates (MINNA MID -	DELT)	III (EN) L	INCINCE.
	·	•	
Northing: (METRES)		(METRES)	
149281.36	481688	S- 50	

\sim	DICKIN	AMAGE	ASSESS	BACKET
·	KIOND	AITIAGE	AJJEJJ	HAILEIAFI

Type of environment of spill site:

7.

No. 0985

Land Swamp water	
Type of environment of which oil has spread:	
Land Swamp water Distance from the nearest sensitive habitat	
☐ Government reserved and designated protected area ☐ Drinking water source ☐ Built up area ☐ Farmlands ☐ Fish Farm/Pond ☐ Fishing net ☐ Others (specify). 9. Containment measures put in place;	[, ,m] [,m] [,m] [,m] [,m] [,m]
□ Booms □ Trench □ Dyke	[Y] [N]/ [Y] [N] [Y] [N]/
Others: NOT APPLICABLE	<u> </u>
10. Any pictures or video coverage?	[Y]/ [N]
11. Was there any disruption to the investigation?	[Y] [N]

If yes give brief description:

THE COMMUNITY REPRESENTATIVE SIGNATORY DISAGREED WITH THE ESTABLISHED CAUSE OF LEAK (SPILL) REING THIRD PARTY INTERFERENCE (DRILLED HOLE) AS AGREED BY OTHER JOINT INVESTIGATION TEAM MEMBERS, AND THEREFORE DIDN'T SIGN THE JIV REPORT.

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

A. Structures / Properties

S/N	Type of Structu	res	Description	Size	Number	Comments
		1 .				
$H \rightarrow$	1) NI-	-XXI	1111	AREA	ME	MPACT
		 	11.011		01	MITTEL



THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: -

No. 0985

B. Crops/Economic Trees

S/N	Types of crops	Young	Medium	Matured	Quantity	Comments
N	ONE	WITHIN	ARI	AC)F IMP	ACT
-	1					

C. Fish/Nets/Ponds


S/N	Fish/Nets/l	Ponds	Descr	iption	Quantity/Size	Comments
N	ONE	W	THIN	ARE	A OF	IMPACT

D. Others (Specify) i.e. Animal Traps

S/N	Others		Description	o n	Quantity/Size	Comments
Ne	INF	W	THIN	ARF	A OF	MPACT
			- - - - - - - - - - 			

E. GRAPHIC DESCRIPTION OF LEAK POINT (Details should be contained in leak repair report)

PLAN SECTION OF 18" ASSA - RUMUEKPE PIPELINE AT AWARA SHOWING LOCATION OF DRILLED HOLE AT 1 0' CLOCK POSITION.



Page 3 of 7

00985 No

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION E. Coordinates (IMPACTED AREA BOUNDARY COORDINATES - MINNA MID-BELT)

	•
Northing (METRES)	Easting (METRES)
149281-38	481694.66
149275-22	481694.65
149 275. 24	481685.41
149284.46	481685.43
, .	
	·
	149275-22 149275-24

G. INCIDENT INF	ORMATION:		NO.	0935	j i	
• Im	ated area of impact_ pact within SPDC R. pact outside R.O.W_ recovered before co	o.w0.	NIL.		barrels	
19. Computation of a. Computation i. ii. iii.	Area (m²) occupied Average Depth (m	nme on site oled free phase oil (on la i by pool of free phase o) of pool of free phase o ed of free phase oil. V	oil No.	APP	barrels	3LE
b. Computati	 i Area (m²) cove ii Average Dept iii Soil type: iv. p_e (effective v. 	trated oil in the soil (V-3 ered by the oil: th (m) below ground sur CLAY porosity of the soil:	face of infiltration of	0.96 oil:	2-015	٦

 $20. \,$ Computation of volume of oil on open water based on standard coloration.

	Thickness (mm)	Percentage coverage	Volume (m3)	
Barely Visible	0.00004			
Silvery	0.00008	N L		
Slight Colour	0.00015			
Bright Colour	0.0003		'	
Dull	0.001	1 22.		•
Dark	0.002	APPL	ILARLE	
Black oil	0.1	7 1 1		
Emulsion (30% Oil)	1			
, ,	Percent Total	100%	Total Volume	NIL_

Spill Factors from USCG FOG (2000 Edition)

bbl



THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 677398

No.

Tick as applicable

***************************************		e of all on open w	iter V _{wa} :	NIL	barrels
21. Calculation of e	_				
i. Oil	type: BONI	MY LIGHT			
ii. E-Fa	actor: 25°	<u> </u>			
iii.					
	rang Jang Vol	ume of evaporate	icil. Viei	0.18	barrels
Oil Type		Bonny Light	Bonny Medium		
		E-Factor	E-Factor	1	
Period Since Oil Spill	<1 day	10%	5%]	
	1-7 days	25%	15%]	
	>7 days	40%	25%]	
VEst(bbls)= 10. Net Total Estimat (bbls) + VrecJ (bbls) VEst(bbls)=	ols) = 0.1	ne VEst(bbls) =	V vap (bbls) + 0.6' 5 - 5 4 + NL	'Vwat (bbls) + Vinf + NIL = O-	(bbls) +Vpool
*Calculation of the res *Conversion of m3 to *Emulsification factor	barrel is Total vo	olume VT (m3) x6	.29		are on site
This report was f investigation repre-	esentative iro	ned on the 2 m	7 / 06 /20	at incident	site by joint
• Departmen	t of Petroleur	n Resources [D	PR]:🔽		
• National Oi	l Spill Detect	ion and Respon	se Agency [NOS	DRA]: 🔽	
State Minis	try of Enviror	nment [SME]:	1		
Nigeria Pol	ice Force [NP	'F]: □			

• Shell Petroleum Development Company [SPDC]: