



Overview: Extent of the spill incident impact at Apra Well 3L Well Head route in Rumuola/Rumudaolu. Picture was taken during JIV of 10<sup>th</sup> May, 2011



Close-up: Tampering with well Head Valve setting on Apra Well 3L Well Head in Rumuola/Rumudaolu. Picture was taken during JIV of 10<sup>th</sup> May, 2011