



Overview: Extent of the spill incident impact over the Assa-Rumekpe pipeline Right of Way in Egbeda. Picture was taken during JIV of 8th May, 2011



Overview: View of part of the spill incident on the 18in Assa-Rumekpe pipeline at Egbeda. Picture was taken during JIV of 8th May, 2011



Close-up: Close up of hacksaw cut on 18in Assa-Rumekpe pipeline at Egbeda. Picture was taken during JIV of 8th May, 2011.



Close-up: Illegally welded point on on 18in Assa-Rumekpe pipeline at Egbeda. Picture was taken during JIV of 9th May, 2011.