



Overview: Extent of the spill incident impact on 12'' Imo River Pipeline at Owaza. Picture was taken during JIV of 12th May, 2011



Overview: Illegally welded point on 12'' Imo River Pipeline at Owaza. Picture was taken during JIV of 12th May, 2011