



Overview: Extent of the spill incident impact on Rumuekpe-Nkpoku pipeline at Rumuekpe. Picture was taken during JIV of 14 May 2011.



Close-up: Illegally welded point on Rumuekpe-Nkpoku pipeline at Rumuekpe. Picture was taken during JIV of 15 May 2011.