



Overview: Extent of the spill incident impact at the 6" Awoba Pipeline route in Owaza . Picture was taken during JIV of 19 May 2011 .



Close-up: Corrosion tear on the 6" Awoba Pipeline at Bille. Picture was taken during JIV of 19 May 2011 .