



Overview: Spill point on the Cawthorne channel Well 29T flowline at Mbiama. Picture was taken during JIV of 18 May 2011



Close-up: Inward dent on the Cawthorne channel Well 29T flowline at Mbiama. Picture was taken during JIV of 18 May 2011