



Overview: Swamp buggy at site covered with fishing nets placed by community members thus delaying response. Picture was taken during JIV of 12<sup>th</sup> May, 2011



Close-up: Closeup of spill point on 10in Ekulama1 pipeline at Freetown. Picture was taken during JIV of 12<sup>th</sup> May, 2011