



Close-up: Dent on 16" Uzere-Eriemu pipeline at Iyede. Picture was taken during Joint Investigation of 16th November, 2011.