



Overview: Part of spill impact on 16" Egbema-Assa pipeline right of way at Assa. Picture was taken during Joint Investigation of 13th November, 2011.



Close-up: Illegal fitting on 16" Egbema-Assa pipeline at Assa. Picture was taken during Joint Investigation of 13th November, 2011.