



Overview: Part of spill impact at 24" Trans Ramos pipeline right of way at Aghoro. Picture was taken during Joint Investigation of 3rd November, 2011.



Overview: Part of spill impact at 24" Trans Ramos pipeline right of way at Aghoro. Picture was taken during Joint Investigation of 3rd November, 2011.