(Note: As practicable as possible the JIT re	port is to be signed in the fi	ield by all the participating parties)
A. GENERAL INFORMATION:		
1. Spill incident Number: 7340		
3. Name of Location KANISO N	IGLL 5L FLOR	VLING @ EGBEMO-ANGALABIRI ELSA 6. LGA EKEREMO
4. Name of nearest community ANGALI	FRIRL 5. State: BAY	CLSA 6. LGA EKEREMO
7. Type of Production facility/Installation _		
B. INCIDENT INFORMATION:		
9. Details of incident a. Date of incident:  b. Date/Period of investigation:	2011@ 1130	14RS 5 & 25/11/2011@1240HRS
c. Description of spill point environn		<u> </u>
☐ Firmed soil	□ Loose soil	☐ Previously excavated area
<b>D</b> Under water	<b>■</b> Swampy	☐ Exposed pipe surface
☐ Well Platform (on Water)		□ Rig
d. Description of leak point (tick as a	'	
☐ Drilled hole	☐ Hack saw cut	☐ Explosive tear,
□ Complete Rupture	☐ Inward dent,	☐ Well head tampering
☐ Failed Weld-on illegal hot tap	<u> </u>	☐ Missing Pipeline/Flowline)
☐ Crude oil theft (illegal bunkering		☐ Third party tampering with Clamp
☐ Third party tampering with val	ve setting,	☐ Third party tampering with flange,
□ External Corrosion		☐ Internal Corrosion
☐ Saver-pit over flow,	☐ Surge vessel overflow	
☐ Flare System/Bund wall Failure		com unit failure
□ Cold vent	☐ Relief valve failure	Others (specify) PINHOLE AND SLIGHT
e. Incident due to:		
☐ Third party interference	Operational	□ Others (specify
f. Spill point coordinates		
Measuring unit Northing:		Easting:
Troiting.		Sub-mag.
99982	M	358507m
		·

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

0062

Page 1 of 9

<sup>\*</sup>This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

# JOINT INVESTIGATION REPORT FOR INCIDENT NO. 2002 734072

C.	RISK ASS	ESSMENT							Ťv.		
	10.	Type of	environment:			.2					
	□ La	nd I	Swamp		Vater	□ Sea	sonal swa	ımp			
	<b>i.</b> '	Type of e	nvironment to	which	oil has spr	ead:					
	□ La	nd I	□ Swamp		Water	□ Riv	er (identi	fy)			
	ii.	Weather o	condition				7				
	□ Rai		Sunny nearest sensit	ive habi	tat						
	□ Dr □ Bu □ Fa ■ Fis □ Ot	inking water hilt up area rmlands sh Farm/Por shing net thers (specif	nd		ed protected	d area	[ %	([m] ([m] ([m] ,m] ,m]			
	<b>∆</b> Bo	oms [	☐ Trench		Dyke						
	□ Oti	hers:	JOT A	400	LICA	BLG	t 				
	13. Any pi	ctures or vie	deo coverage	?			[V]	[N]			
	14. Was th	ere any disr	ruption to the	investig	ation?		[Y]				
If yo	es give brief	description	:								
	NOT	· A (	2961	<u> </u>	3LE						_
D.		MBERS OF		ES, IF	ANY, FOU	IND WIT	HIN THI	E AREA O	F SPRE	EAD OF OIL	
S/N		Structures		ription	Size	Niii	mber		Com	ments	-
5/13	Турс ОГ	Silucture	Desci	- Prion	Jize -	1,00			Com		
		<u> </u>			<del>                                     </del>				-		
	5 / 0	16	, , , , , ,			ARC	1	OF		MAPH (	1

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1062 734072

#### 16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
1	MANGROVE		YES	Yes	LOT	

#### 17. Fish/Nets/Ponds

S/N	Fish/Nets	/Ponds	Descrip	otion	Quant	ity/Size	Comments
N	ONE	WIT	HIN	ARCA	VOF	IMI	ACT

18. Others (Specify) i.e. Animal Traps

S/N	Others		Descript	ion	uanti	ty/Size	Commer	ts
11	206	14/1	THIM	AREA	OF	100	BAC	7
<u>M</u>	1/40	00:		7170	, ,	( / / /	7,0	

**E. GRAPHIC DESCRIPTION OF LEAK POINT** (Overview sketch of the site should be added as an appendix 1)

FROM
WELL HEAD

WELDED

POINT OF POINT OF LEAKING (2)

LEAKAGE (1)

LEAKAGE (2)

DOINT

LEAKAGE (3)

DOINT

LEAKAGE (3)

DOINT

LEAKAGE (4)

DOINT

DOINT

LEAKAGE (1)

DOINT

DOINT

LEAKAGE (1)

DOINT

DOI

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0062 734072

# F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing	Easting
SP	99982	358507
/	99968	358458
2	99936	358358
3	99996	358547
4	100 035	358535
5	100030	358628
6	100037	358658
7	100055	358689
8	99933	358607
9	99901	358652
10	79869	358678
11	99919	358310
12	99890	358320

#### **G. INCIDENT INFORMATION:**

20. Impacted Area Details

• Total ca	culated area of impact _	31849	· 5 M	
Impact v	within SPDC R.O.W	5977,	59 M2	
• Impact	outside R.O.W	25871	.92 m2	
21. Volume of oil re	ecovered before comple	tion of JIV (V <sub>rec</sub> J):		
	Recove	red oil V <sub>rec</sub> j:	NIL	barrels
20. <u>Computation of</u>	the residual volume on	site		
a. Computation of v i. Are	volume of pool of free phase a (m <sup>2</sup> ) occupied by pool of	se oil (on land or confined of free phase oil	water body). NIL	
ii. Av	erage Depth (m) of pool of ulsification factor: NOT	free phase oil NO		310
	iv. Volume of pool of f	ree phase oil. V <sub>pool</sub> :	NIL	barrels

0062 784072 JOINT INVESTIGATION REPORT FOR INCIDENT NO:

- b. Computation of volume of infiltrated oil in the soil (V<sub>inf</sub>).
  - i. Area (m<sup>2</sup>) covered by the oil:
  - ii. Area of the pool of free phase oil in touch with soil: NOT APPLICAR
  - iii. Average Depth (m) below ground surface of infiltration of oil: NOT APPLIC
  - iv. Soil type: NOT KPPLICABLE
  - v. Pe (effective porosity of the soil). NOT APPLICABLE

v. Volume of infiltrated oil. V <sub>inf</sub>	NIL	barrels
--	-----	---------

- 21. Computation of volume of oil on open water based on standard coloration.

  i. Total area of oil on open water: 31849.5 m²
  - Table of average depth of oil on water based on coloration ii.

	Thickness (mm)	Percentage coverage	Volume (m3)	
Barely Visible	0.00004	20 %	0.000254796	]
Silvery	0.00008	15%	0-000382194	
Slight Color	0.00015	200/0	0.000955485	
Bright Color	0.0003			
Dull	0.001	15%	0.004777425	]
Dark	0.002	5%	0-003184950	}
Black oil	0.1	15%	0.477742500	]
Emulsion (30% Oil)	1	10%	3.184950000	
	Percent Total	100%	Total Volume 3	67 mm <sup>3</sup>

iii. Volume of oil on open water. Vwat:	23-10 barrels
---	---------------

- 22. Calculation of evaporated volume:
  - Oil type: BONNY MEDIUM
  - E-Factor: 15% ii.

iii. Volume of evaporated oil. V evap:	4.08 barrels

Evaporation Factors (E-Factor) for SPDC Crude oil							
Oil Type	Days on site	Bonny Light	Bonny Medium				
Period Since Oil Spill	< 1 day	10%	5%				
	1-7 days	25%	15%				
	> 7 days	40%	25%				

23. Gross Total Estimated Spilled Volume  $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_$  $V_{pool}$  (bbls) +  $V_{recJ}$  (bbls)

JOINT INVESTIGATION REPORT FOR INCIDENT NO. 0062 734072

$\frac{V_{Est}(bbls)=}{27.2 BBLs}$	
24. Net Total Estimated Spilled Volume V Est(bbls) = Vevap(b	$(bbls) + 0.6*V_{wat} (bbls) + V_{inf} (bbls) +$
V <sub>pool</sub> (bbls) + V <sub>recl</sub> (bbls)	
VEst(bbls)= 17.9BBLS	

#### 25. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact After the initial response and therefore recommend that the site be closed out □
B. Investigation of the incident site showed that there is residual impact on site requiring further works □

#### 26 Signatories

This report was filled and signed on the  $\frac{3}{5}$   $\frac{25}{1}$   $\frac{1}{20}$  at incident site by joint investigation representatives from

- Host Community
- Department of Petroleum Resources [DPR]: □
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:
- Shell Petroleum Development Company [SPDC]:

Tick as applicable


<sup>\*</sup>Calculation of the respective estimated volume is to be done using the new spill estimation software on site

<sup>\*</sup>Conversion of m3 to barrels is Total volume VT (m3) x 6.29

<sup>\*</sup>Emulsification factor for spill on water to consider is 60% of volume of oil.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0062 734072

20. Appendix 1: Overview sketch of the site



Page 7 of 9

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 00627 34072

# 21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
13	99953	358300
14	99900	358371
15	99966	358347
16	99931	358 473
17	100001	358446
18	99907	358536
19	100019	358492
20	99934	358579
21	100033	358531
22	100034	358532
23	150051	358515
24	99935	358 611
25	99904	358656
26	99872	358682
27	99978	358608
28	100012	358636
29	100041	358695
30	100052	358651