JOINT INVESTIGATION REPORT FOR INCIDENT	NO:723263
(Note: As practicable as possible the JIT report is to be signed in	
A. GENERAL INFORMATION:	y and the purificipating parties)
1. Spill incident Number: 723263 2.Ty	una afimalidament and Chill
2 Name of Land 1/1 Co. 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	ype of incident. OLL SPILL
3. Name of Location /6" SOUTH - FORCADOS TR	MAKLINE AT OVIRI-OLOMU
4. Name of nearest community OVIRI-OLOMU 5. State: 1	SELTA 6. LGA UNHELLI SOUTH
7. Type of Production facility/Installation TRUNKLINE	
B. INCIDENT INFORMATION:	•
9. Details of incident a. Date of incident:05 <sup>T#</sup> october, 2	
b. Date/Period of investigation: 2 <sup>T#</sup> FEBRUARY 201	2 AND 14TH FEBRUARY 2012@1145HS
c. Description of spill point environment	•
☐ Firmed soil ☐ Loose soil	☐ Previously excavated area
☐ Under water	☐ Exposed pipe surface
□ Well Platform (on Water)	□ Rig
d. Description of leak point (tick as applicable);	
□ Drilled hole □ Hack saw cut	☐ Explosive tear,
□ Complete Rupture □ Inward dent,	☐ Well head tampering
☐ Failed Weld-on illegal hot tap valve,	☐ Missing Pipeline/Flowline)
☐ Crude oil theft (illegal bunkering) point,	Third party tampering with Clamp
☐ Third party tampering with valve setting,	Third party tampering with flange,
External Corrosion	☐ Internal Corrosion
☐ Saver-pit over flow, ☐ Surge vessel overfl	ow, Dutward dent
□ Flare System/Bund wall Failure □ Valve Failure	com unit failure
□ Cold vent □ Relief valve failure	Others (specify)
e. Incident due to:	
☐ Third party interference	☐ Others (specify
f. Spill point coordinates	
Measuring unit	
Northing:	Easting:
146693m	384029M

# THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO. 0098 723263

Type o	of environment:		.5				
nd	□ Swamp	□ Water	<b>⊠</b> Seas	onal swa	amp		
Type of	environment to	which oil has sp	read:				
nd	Swamp	□ Water	□ Rive	r (identi	fy)		
Weather	r condition						
		ve habitat	•				
inking wa ilt up area rmlands th Farm/P thing net hers (spec	ater source ond cify).		ed area	30   114   114	,m] ,m] ,m] ,m]		
		·					
ners:				_			
ctures or v	video coverage?			آند]	[N]		
ere any di	sruption to the i	nvestigation?		[Y]	[₩]		
descriptio	on:				·		
10 T	AP	PLICA	BLE				
	Type of  Type of  Meather  ming the from the  overnment inking was the Farm/P thing net thers (spectament me  oms  hers:  ctures or was  description	Type of environment to  Make Swamp  Weather condition  ming Sunny the from the nearest sensitive overnment reserved and desinking water source to the source of the source	Type of environment to which oil has spend	Type of environment to which oil has spread:  Ind Swamp Water Rive  Weather condition  Ining Sunny  The from the nearest sensitive habitat  Invernment reserved and designated protected area inking water source  If you area  If	Type of environment to which oil has spread:  Ind Swamp Water River (identified and Swamp Water Condition River (identified and Swamp River (identified	Type of environment to which oil has spread:  Ind Swamp Water River (identify)  Weather condition  Ining Sunny The from the nearest sensitive habitat  Invernment reserved and designated protected area in the parea	Type of environment to which oil has spread:  Ind Swamp   Water   River (identify)    Weather condition  Thing Sunny  The from the nearest sensitive habitat  Ind All Mile miles in the served and designated protected area in the parea   Mile miles in the parea   Miles mil

15.	Structures /	Properties

S/N	Type of Structures	Description	Size	Number		Comments
					•	
ļ						
		hi <del>ce in al</del>	A.F	EA	OF	IMPACT
	NONE 1	MIN HIM	77.	CA	OF_	July 201
		<u></u>		<u> </u>		
<u> </u>						
L				]		

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0098 723263

#### 16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
Di	MANG ROVE	\	\	/	LoT	IMPACTED
OF	RAPHIA PALM			<b>/</b>	LOT	IMPACTED


#### 17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
01	FISH PONDS		87	IMPACTED

#### 18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	¿uantity/Size	Comments
ol	FISH TRAPS		20	IMPACTED

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0098 723263

#### F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing	Easting
	146682	384036
2_	146678	384023
3	146706	384020
4	146704	384039
5	146634	384029
6	146637	383 982
7	146650	384003
8	146685	383981
9	146723	383971
10	146754	383993
11	146777	384011
12	146704	384007
13	146673	3-84055

#### \* G. INCIDENT INFORMATION:

20. Impacted Area Details

Total calculated area of impact	12477-50 MT
Impact within SPDC R.O.W	2808·77 m²
Impact outside R.O.W	9668·73 M <sup>2</sup>

21. Volume of oil recovered before completion of JIV (V...)

LEAVES	Recovered oil V <sub>rec</sub> r	NIL	barrels
20. Computation of the res	of pool of free phase oil (on land or confine phase oil	ined water body). 2808.77 0.002	<u></u>
AVERAGE THICKNESS IV. Y	Volume of pool of free phase oil. V pool:	14.13	barrels

Page 4 of 9

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0093 723263

- b. Computation of volume of infiltrated oil in the soil  $(V_{inf})$ .
  - i. Area (m²) covered by the oil:
  - ii. Area of the pool of free phase oil in touch with soil: NIL
  - iii. Average Depth (m) below ground surface of infiltration of oil: NOT APPLICABLE
  - iv. Soil type: NOT APPLICABLE
  - v. P. (effective porosity of the soil). NOT APPLICABLE

ſ	iv.	Volume of infiltrated oil. Vinf	NIL	barrels
- 1	i	·	, , , , , , , , , , , , , , , , , , , ,	

- 21. Computation of volume of oil on open water based on standard coloration.
- i. Total area of oil on open water:
- ii. Table of average depth of oil on water based on coloration \*

	Thickness (mm)	Percentage coverage	Volume (m3)	
Barely Visible	0.00004		<b>/</b> i	⊿
Silvery	0.00008			
Slight Color	0.00015			
Bright Color	0.0003			
Dull	0.001			
Dark	0.002			
Black oil	0.1			
Emulsion (30% Oil)	1	/		
	Percent Total	100%	Total Volume N	L bbl
	iii. Volume of o	il on open water. Vwat:	NIL	barrels

- 22. Calculation of evaporated volume:
  - i. Oil type: BONNY MEDIUM
  - ii. E-Factor: 25 %

iii. Volume of evaporated oil. V evap:	4.71	barrels


Evaporation Factors (E-Factor) for SPDC Crude oil				
Oil Type	Days on site	Bonny Light	Bonny Medium	
Period Since Oil Spill	< 1 day	10%	5%	
-	1-7 days	25%	15%	
	> 7 days	40%	25%	

23. Gross Total Estimated Spilled Volume  $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recl}(bbls) + O O (BBLs)$ 

	VESTIGATION REPORT FOR INCIDENT NO: 725765
V <sub>Est</sub> (bbls)=	18.85BBL
24. Net To	tal Estimated Spilled Volume V Est(bbls) = Vevap(bbls) + 0.6*Vwat (bbls) + Vinf (bbls) + obls) + Vec (bbls) + oct (BBLs)
VEst(bbls)=	18.85 BBLs
*Conversion of m	the respective estimated volume is to be done using the new spill estimation software on site 13 to barrels is Total volume VT (m3) x 6.29 actor for spill on water to consider is 60% of volume of oil.
25. GENEI	RAL STATUS OF THE SITE .
	vestigation of the incident site found that there is no residual impact. After the sponse and therefore recommend that the site be closed out $\Box$
	works
26 Signat	ories
This report	was filled and signed on the 14/02/2012 at incident site by joint a representatives from
This report investigation	was filled and signed on the 14/02/2012 at incident site by joint
This report investigation  • Host Co	was filled and signed on the 14/02/2012 at incident site by joint representatives from
This report investigation  Host Co Depart	was filled and signed on the 14/02/2012 at incident site by joint representatives from
This report investigation  Host Co Depart  Nations	was filled and signed on the 14/02/2012 at incident site by joint representatives from ommunity \square ment of Petroleum Resources [DPR]:
This report investigation  Host Co Depart  Nations State M	was filled and signed on the 14/02/2012 at incident site by joint representatives from ommunity  ment of Petroleum Resources [DPR]:
This report investigation  Host Co Depart  Nations State M Nigeria	was filled and signed on the 14/02/2012 at incident site by joint representatives from ommunity  ment of Petroleum Resources [DPR]:  al Oil Spill Detection and Response Agency [NOSDRA]:  linistry of Environment [SME]:

JOINT INVESTIGATION REPORT FOR INCIDENT NO:\_\_\_\_\_

20. Appendix 1: Overview sketch of the site



NOTE: AREA OF LIGHT IMPACT
REFERS TO WEATHERED
CRUDE OIL STAINED
LEAF DROPPINGS ON
NON-IMPACTED SOIL \$
POND SURFACES.

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

0098 7

723263

### 21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
14	146662	384664
15	146657	384081
16	146640	3 84118
17	146631	384103
18	146697	384676
19	146740	384097
20	146749	384118
21	146758	384 <i>8</i> 98
22	146747	38483
23	146723	<b>3</b> 84072
24	146715	384045
25	146693	384029
<u>/</u>		