THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 2. Type of incident* 51L 1. Spill incident Number: UMUECHEM - NKPOKU PIPELINE 3. Name of Location 4. Name of nearest community GWURUTA 5. State: RWERS 6. LGA 7. Type of Production facility/Installation PIPRLINE 8. Asset owner/District UKIPINESP **B. INCIDENT INFORMATION:** 9. Details of incident a. Date of incident: 18 TH October b. Date/Period of investigation: 2157 c. Description of spill point environment Firmed soil Previously excavated area □ Loose soil ☐ Under water □ Swampy ☐ Exposed pipe surface ☐ Well Platform (on Water) □ Rig d. Description of leak point (tick as applicable); ☐ Drilled hole ☐ Hack saw cut □ Explosive tear, □ Complete Rupture ☐ Inward dent, □ Well head tampering ■ Failed Weld-on illegal hot tap valve, ☐ Missing Pipeline/Flowline) ☐ Crude oil theft (illegal bunkering) point, ☐ Third party tampering with Clamp ☐ Third party tampering with valve setting, ☐ Third party tampering with flange, □ External Corrosion □ Internal Corrosion □ Saver-pit over flow, □ Surge vessel overflow, □ Outward dent ☐ Flare System/Bund wall Failure ☐ Valve Failure com unit failure

f. S _l	pill point coordinates Measuring unit MeTex	Ammin	MID -BEIT.
	Northing:		Easting:
	108643.61		506966 95 95

□ Others (specify) NOT APPLICABLE

□ Others (specify Not APPLICABLE.

□ Relief valve failure

☐ Operational

Page 1 of 9

□ Cold vent

e. Incident due to:

Third party interference

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0124 728747

C.	RISK	ASSESSMEN	т			
	10.	Туре о	f environment:			
		Land	□ Swamp	□ Water	☐ Seasonal swam	p
		i. Type of	environment to w	hich oil has spread	l:	
		Land	□ Swamp	□ Water	☐ River (identify))
		ii. Weather	condition			
		☐ Raining Distance from the	Sunny e nearest sensitive	habitat		
☐ Government reserved and designated protected area ☐ Drinking water source ☐ Built up area ☐ Farmlands ☐ Fish Farm/Pond ☐ Fishing net ☐ Others (specify). Not KPPLUSE: 12. Containment measures put in place;			[Mil. [Mil. [S	.m] ,m] ,m]		
	I	□ Booms	Trench	□ Dyke		
	I	ロ Others: <u>へ</u> て	it applica	BLE.	· · · · · ·	
	13. A	Any pictures or v	video coverage?		[Y]	[N]
	14. V	Vas there any dis	sruption to the inv	estigation?	[Y]	[N]
If y	es give	e brief description	on:			
		No	7 A	PPI	ARI	
		1 2 0	1	116		

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number		Comments
	Mario	1150		X 20.1		121 DL CT
	HOIRE	KIL IT		TKEA	01	THINCI.
	·					

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	Crossing	NU_			10m × [m	
	1017	MIGHT	AC	RA 8	(X)PA	ET

17. Fish/Nets/Ponds


NONE WITHIN AREA OF IMPA	Comments	Quantity/Size	Description	Fish/Nets/Ponds	S/N
	MPACT	TREA EF	THIN	ONE M	N

18. Others (Specify) i.e. Animal Traps

S/N Others	Description	Quantity/Size	Comments
NONE	WITHEN	ARCA OF	IMPACT.

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)

Unueenem - NKPOKY "IGNURUITA WITH



JOINT INVESTIGATION REPORT FOR INCIDENT NO:

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing	Easting
124	108640.54	506966.95
125	108640.55	506963.87
156	108643.64	506957.71
127	108649 · 79	506954.64
128	108659.00	506957.75
129	108658.99	506960.83
130	108662.06	506960.83
131	18677. 43	506954.71
132	108680.50	506957.79
133	108686 · 64	506957.81
135	108680.49	506960.88
136	108680.49	506963.96
137	108652-82	506970.06

G. INCIDENT INFORMATION:

20	Impacted	1 4 400	Dataila
/U	imnacied	ГАТСЯ	LIETATIS

	Total calculated area of impact O O F	tla	_
	Impact within SPDC R.O.W		_
	Impact outside R.O.W		_
21.	Volume of oil recovered before completion of JIV (V _{rec.j}):		
	Recovered oil V _{ree.j} ;	NIL	barrels
20.	Computation of the residual volume on site		
a.	Computation of volume of pool of free phase oil (on land or confined i. Area (m²) occupied by pool of free phase oil	water body). $6m^2$	_
	ii. Average Depth (m) of pool of free phase oil	0.02M	-
	iii. Emulsification factor:		
	iv. Volume of pool of free phase oil. V _{pool} :	0 76	barrels

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0124 728747

b. С	omputation	of volume	of infiltrated	oil in	the soil	V_{in}	ď.
------	------------	-----------	----------------	--------	----------	----------	----

i. Area (m²) covered by the oil: 400 m²

ii. Area of the pool of free phase oil in touch with soil: 0.01

iii. Average Depth (m) below ground surface of infiltration of oil:

iv. Soil type: CLAY

v. $P_{\rm e}$ (effective porosity of the soil).

iv. Volume of infiltrated oil. Vinf 2.01 barrels

21. Computation of volume of oil on open water based on standard coloration.

i. Total area of oil on open water: NOT APPLICABLE

ii. Table of average depth of oil on water based on coloration

	Thickness (mm)	Percentage coverage	Volume (m3)		
Barely Visible	0.00004				
Silvery	80000.0		•		
Slight Color	0.00015	70			
Bright Color	0.0003				
Dull	0.001	X 201 6	ARICI		
Dark	0.002	#\\\\\\			
Black oil	0.1				
Emulsion (30% Oil)	1				
	Percent Total	100%	Total Volume	مدرك	bbl

	iii. Volume of oil on open water. Vwat:	NIL	barrels
--	---	-----	---------

22. Calculation of evaporated volume:

i. Oil type: BENNY MEDIUM

ii. E-Factor: 15 %

iii. Volume of evaporated oil. V evap:	0.50	barrels

Evapo	ration Factors (E-Fa	actor) for SPDC Crue	de oil
Oil Type	Days on site	Bonny Light	Bonny Medium
Period Since Oil Spill	< 1 day	10%	5%
	1-7 days	25%	15%
	> 7 days	40%	25%

23. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recl}(bbls) +$

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0124 728747

$\frac{\mathbf{V}_{Est}(bbls)=}{\mathbf{C}}$	1 + 42.0	411 ∟ +	2001	+0	75	+ MIL	- =	3.26	Breezes.
			led Volum	ne V _{Est} (b	<u>bls)</u> = V	_{evap} (bbls)	+ 0.6*	V _{wat} (bbls)	$+ V_{inf}$ (bbls) $+$
V _{pool}	$(bbls) + V_{re}$	oci (ppis)		1,1 1					
VEst(bbls)=	3.26	BARLE	es						

25. GENERAL STATUS OF THE SITE

- A. Joint investigation of the incident site found that there is no residual impact. After the initial response and therefore recommend that the site be closed out □
- B. Investigation of the incident site showed that there is residual impact on site requiring further works

26 Signatories

This report was filled and signed on the investigation representatives from

- Host Community
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:

 ✓
- Nigeria Police Force [NPF]:
- Shell Petroleum Development Company [SPDC]: ☑

Tick as applicable


^{*}Calculation of the respective estimated volume is to be done using the new spill estimation software on site

^{*}Conversion of m3 to barrels is Total volume VT (m3) x 6.29

^{*}Emulsification factor for spill on water to consider is 60% of volume of oil.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 728747

20. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 728 724

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION (NINNA NIL-SETT.)

S/N	Northing C.	Easting (McGC)
13/14	Northing (MGTEK)	Easting (MCTSC)
		2)/
		(KS M)
		(),5
		x /
		with the second
		.6/
		o de tre
	¥	
	Reliable to the second	
	15	
	 	
	1	
	/	
-/	<u></u>	
_		