

<u>Close-up:</u> Illegal fitting on 8" Umuechem-Nkpoku pipeline at Igwuruta. Picture was taken during Joint Investigation of 21st October, 2011.

1