



Overview: Location of spill on 6" Obigbo North pipeline right of way at Ogale. Picture taken during Joint Investigation of 3<sup>rd</sup> October, 2011.



Close-up: Spill due hacksaw cut on 6" Obigbo North pipeline at Ogale. Picture taken during Joint Investigation of 3<sup>rd</sup> October, 2011.