JOINT INVESTIGATION REPORT FOR INCIDENT NO: _____

(Note: As practicable as possible the JIT re	port is to be signed in the fi	eld by all the participating parties)
A. GENERAL INFORMATION:		
1. Spill incident Number: 7232	.50 2.Type of	incident* OIL SPILL
		ADOS PRPELING @ BATAN
4. Name of nearest community RAT	4N 5. State: D€1	LTA 6. LGA WARRI-SOUTH WEST
7. Type of Production facility/Installation _	IRUNKLINE 8. AS	set owner/District PIPELING
B. INCIDENT INFORMATION:		
9. Details of incident a. Date of incident: 04 1 10 1	2011 @ 1900	0HRS MID 13/10/2011@12401 1230HRSA
c. Description of spill point environs□ Firmed soil	nent Loose soil	☐ Previously excavated area
Winder water	☐ Swampy	□ Exposed pipe surface
☐ Well Platform (on Water) d. Description of leak point (tick as a	• •	□ Rig
□ Drilled hole	☐ Hack saw cut	☐ Explosive tear,
☐ Complete Rupture	Inward dent, (OLD)	☐ Well head tampering
☐ Failed Weld-on illegal hot tap	valve,	☐ Missing Pipeline/Flowline)
☐ Crude oil theft (illegal bunkering	ng) point,	☐ Third party tampering with Clamp
☐ Third party tampering with val	ve setting,	☐ Third party tampering with flange,
□ External Corrosion		☐ Internal Corrosion
☐ Saver-pit over flow,	☐ Surge vessel overflow,	☐ Outward dent
☐ Flare System/Bund wall Failur	e 🗖 Valve Failure	□ com unit failure
□ Cold vent	☐ Relief valve failure	☐ Others (specify)
e. Incident due to: Third party interference	□ Operational	☐ Others (specify
f. Spill point coordinates Measuring unit Northing:		Easting: 343358 _M

Page 1 of 9

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0052 723250

C.	RISK ASSESSMENT				•
	10. Type of env	ironment:			
	□ Land □	Swamp 🖼	Vater □	l Seasonal swamp	
	i. Type of envi	ronment to which o	oil has spread:		
	□ Land □ S	Swamp 💆	Vater □	l River (identify)	
	ii. Weather con	dition			
	Maining 11. Distance from the nea	Sunny arest sensitive habit	tat		
	Government rese Drinking water so Built up area Farmlands Fish Farm/Pond Fishing net Others (specify). Containment measure	ource	d protected area	[N, L, m] [6, m] [120, m] [10, m] [0, m] [0, m]	
	Booms 🗆		•		
	Others: 13. Any pictures or video	coverage?			
	14. Was there any disrupt	tion to the investig	ation?	[Y] [N]	
If y	es give brief description:				
	NOT A	t PPLIC	ABLE	3 ·	
D.	TYPE/NUMBERS OF PI	ROPERTIES, IF	ANY, FOUND	WITHIN THE AREA OF	SPREAD OF OIL
	15. Structures / Propert	ies			
S/N	Type of Structures	Description	Size	Number	Comments

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0052 723250

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	MANGROVE		765	7/65	LOT	
				7		
[-/						

17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	NETS		150	
2_	F15 H	SEUGRAL TUPE	LOT	
			7	

18. Others (Specify) i.e. Animal Traps

S/N Others	Description	Quantity/Size	Comments
NONEW	THIM AREA	OFIM	PACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix1)

28 INCH TRANS FORCADOS PIPERING

128"
INWARD DENT
(SPILL POINT)

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED 101117 INTERTICATION REPORT FOR INCIDENT NO. 10152 723250

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing	Easting
SP	170745	343358
	170744	343367
	170788	343367
	170724	343324
	170737	343321
	170662	343168
	170560	342 944
	170451	342706
	170 378	342 521
	172061	343336
	170897	342366
	170944	342025
	170473	343737

G. INCIDENT INFORMATION:

Impacted Area Deta	ı	ŀ
--------------------------------------	---	---

	• Total calculated area of impact 1,367	905.82 M2
	Impact within SPDC R.O.W	80 M2
	• Impact outside R.O.W 1,249,8	$325.82m^2$
21. <u>Vol</u>	ume of oil recovered before completion of JIV (Vrec.j):	
	Recovered oil V _{rec} J.	NIL barrels
20. <u>Cor</u>	nputation of the residual volume on site	
a. Con	nputation of volume of pool of free phase oil (on land or con i. Area (m²) occupied by pool of free phase oil	
	ii. Average Depth (m) of pool of free phase oil	0.004M
	iii. Emulsification factor: 60 %	
i.	iv. Volume of pool of free phase oil. V_{pool} :	7.93 barrels

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED 0052 JOINT INVESTIGATION REPORT FOR INCIDENT NO: b. Computation of volume of infiltrated oil in the soil (V_{inf}). i. Area (m²) covered by the oil: NIL ii. Area of the pool of free phase oil in touch with soil: iii. Average Depth (m) below ground surface of infiltration of oil: NOT APPLICABLE iv. Soil type: NOT APPLICABLE Pe (effective porosity of the soil). NOT APPLICABLE Volume of infiltrated oil. Vinf 21. Computation of volume of oil on open water based on standard coloration. Total area of oil on open water: 1,367,117.82 M2 Table of average depth of oil on water based on coloration * ii. **Thickness** Percentage (mm) Volume (m3) 0.00382793 **Barely Visible** 0.00004 Silvery 0.00008 0.092280453 Slight Color 0.00015 0-020506767 **Bright Color** 0.0003 0 314437098 Dull 0.001 0136711782 Dark 0.002 20.50676726 Black oil 0.1 Emulsion (30% Oil) 1 2Li 07 **Total Volume** Percent Total 100%

124	iii. Volume of oil on open water. Vwat	132.54	barrei
-----	--	--------	--------

22. Calculation of evaporated volume:

i. Oil type: BONNY MEDIUM

ii. E-Factor: 25%

iii. Volume of evaporated oil. V evap:	46.82 barrels
--	---------------

Evaporation Factors (E-Factor) for SPDC Crude oil					
Oil Type	Days on site	Bonny Light	Bonny		
			Medium		
Period Since Oil	< 1 day	10%	5%		
Spill			1		
	1-7 days	25%	15%		
	> 7 days	40%	25%		

23. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls)$

JOINT INVESTIGATION REPORT FOR INCIDENT NO: UU52 723250

V _{Est} (bbls)=	187.30	O BBLs			
24. Net 7	Total Estimated Spill	ed Volume V Est(b)	bls) = $V_{evap}(bbls)$	$(bbls) + 0.6 V_{wat}$	$+ V_{inf}$ (bbls) $+$
	$(bbls) + V_{recJ} (bbls)$		•		
VEst(bbls)=	13428	BBLs		· · · · · · · · · · · · · · · · · · ·	

25. GENERAL STATUS OF THE SITE

A.	Joint investigation of the incident site found that there is no residual impact. After the initial response and therefore recommend that the site be closed out.
В.	Investigation of the incident site showed that there is residual impact on site requiring further works

26 Signatories

This report was filled and signed on the $\frac{3}{13}$ /10/2011 at incident site by joint investigation representatives from

- Host Community
- Department of Petroleum Resources [DPR]: □
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:
- Shell Petroleum Development Company [SPDC]:

Tick as applicable

^{*}Calculation of the respective estimated volume is to be done using the new spill estimation software on site

^{*}Conversion of m3 to barrels is Total volume VT (m3) x 6.29

^{*}Emulsification factor for spill on water to consider is 60% of volume of oil.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0052 723250

20. Appendix 1: Overview sketch of the site

Location: 28 INCH TRANS FORCADOS PIPELINE @ BATAN
AS AT OBLIO[2011 28 INCH TRANS FORCADOS PIPELINE CONTAINMENIT RIVER BOOMS WATER SPILL POINT IMPACTED SECTION SPDC RIGHT OF WAY

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED 723250 JOINT INVESTIGATION REPORT FOR INCIDENT NO:

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
	170193	344599
	170004	344252
	169811	344484
	169550	344010
	168106	344779
	169160	343579
	169524	343392
	169 678	344 353
	172459	345979
	172001	345051
	171406	344629
	170797	343461
	170773	343428
	170736	343396
	172428	3459/6
	168476	344989
	170984	344684
	170989	344869

OVERVIEW OF SITE SKETCH AS AT 13/10/2011 28 INCH TRANS FORCADOS PIPELINE @ BATAN

APPENDIX 3

TOTAL AREA = 1367,405 8 OF IMPACT SLIGHT COLOR IMPACT COMMUNITY JETTY SLIGHT-COLOR BATAN FLOWSTATION SLIGHT FREE PHASE OIL WITHWIBOOM IMPACT CONTAINMENT RIVER BOOMS FAST FLOWING BLACK OIL DULL IMPACT IMPACT EGWA CONTAINMENT WELL 22 BOOM FAST FLOWING TIDAL WATER